

**Representative Daniel McCay** proposes the following substitute bill:

**SCHOOL SECURITY LOCKS**

2018 GENERAL SESSION

STATE OF UTAH

**Chief Sponsor: Todd Weiler**

House Sponsor: Daniel McCay

---

---

**LONG TITLE**

**General Description:**

This bill amends provisions of the State Construction and Fire Codes Act.

**Highlighted Provisions:**

This bill:

▶ amends the International Building Code and International Fire Code regarding:

• hardware height on a door for certain occupancies for purposes of a lockdown or a lockdown drill; and

• door operations provisions for locks and bolt locks, and latching and unlatching, for certain occupancies for purposes of a lockdown or a lockdown drill; and

▶ makes technical changes.

**Money Appropriated in this Bill:**

None

**Other Special Clauses:**

None

**Utah Code Sections Affected:**

AMENDS:

**15A-3-105**, as last amended by Laws of Utah 2016, Chapter 249

**15A-5-205**, as last amended by Laws of Utah 2016, Chapter 216



26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56

---

---

*Be it enacted by the Legislature of the state of Utah:*

Section 1. Section **15A-3-105** is amended to read:

**15A-3-105. Amendments to Chapters 10 through 12 of IBC.**

(1) In IBC, Section 1010.1.9, an exception is added as follows: "Exception: Group E occupancies for purposes of a lockdown or a lockdown drill in accordance with Section 1010.1.9.5 Exception 5."

(2) In IBC, Section 1010.1.9.2, "Exception:" is deleted and replaced with "Exceptions: 1."

(3) In IBC, Section 1010.1.9.2, a new Exception 2 is added as follows: "2. Group E occupancies for purposes of a lockdown or a lockdown drill may have one lock below 34 inches in accordance with Section 1010.1.9.5 Exception 5."

(4) In IBC, Section 1010.1.9.3, a new number 6 is added as follows: "6. Group E occupancies for purposes of a lockdown or a lockdown drill in accordance with Section 1010.1.9.5 Exception 5."

(5) In IBC, Section 1010.1.9.4, a new exception 6 is added as follows: "6. Group E occupancies for purposes of a lockdown or a lockdown drill in accordance with Section 1010.1.9.5 Exception 5."

(6) In IBC, Section 1010.1.9.5, a new exception 5 is added as follows: "5. Group E occupancies may have a second lock on classrooms for purposes of a lockdown or lockdown drill, if:

5.1 The application of the lock is approved by the code official.

5.2 The unlatching of any door or leaf does not require more than two operations.

5.3 The lock can be released from the opposite side of the door on which it is installed.

5.4 The lock is only applied during lockdown or during a lockdown drill.

5.5 The lock complies with all other state and federal regulations, including the Americans with Disabilities Act of 1990, 42 U.S.C. Sec. 12101 et seq."

[(+)] (7) In IBC, Section 1010.1.9.6, a new number 9 is added as follows: " 9. The secure area or unit with special egress locks shall be located at the level of exit discharge in Type V construction."

[(2)] (8) In IBC, Section 1011.5.2, exception 3 is deleted and replaced with the

57 following: " 3. In Group R-3 occupancies, within dwelling units in Group R-2 occupancies,  
58 and in Group U occupancies that are accessory to a Group R-3 occupancy, or accessory to  
59 individual dwelling units in Group R-2 occupancies, the maximum riser height shall be 8  
60 inches (203 mm) and the minimum tread depth shall be 9 inches (229 mm). The minimum  
61 winder tread depth at the walk line shall be 10 inches (254 mm), and the minimum winder  
62 tread depth shall be 6 inches (152 mm). A nosing not less than 0.75 inch (19.1 mm) but not  
63 more than 1.25 inches (32 mm) shall be provided on stairways with solid risers where the tread  
64 depth is less than 10 inches (254 mm)."

65 [~~(3)~~] (9) In IBC, Section 1011.11, a new exception 5 is added as follows: " 5. In  
66 occupancies in Group R-3, as applicable in Section 101.2 and in occupancies in Group U,  
67 which are accessory to an occupancy in Group R-3, as applicable in Section 101.2, handrails  
68 shall be provided on at least one side of stairways consisting of four or more risers."

69 [~~(4)~~] (10) In IBC, Section 1013.5, the words ", including when the building may not be  
70 fully occupied" are added at the end of the sentence.

71 [~~(5)~~] (11) IBC, Section 1025, is deleted.

72 [~~(6)~~] (12) In IBC, Section 1029.14, exception 2 is deleted.

73 [~~(7)~~] (13) In IBC, Section 1109.8, the following words "shall be capable of operation  
74 without a key and" are inserted in the second sentence between the words "lift" and "shall".

75 [~~(8)~~] (14) In IBC, Section 1208.4, subparagraph 1 is deleted and replaced with the  
76 following: "1. The unit shall have a living room of not less than 165 square feet (15.3 m2) of  
77 floor area. An additional 100 square feet (9.3 m2) of floor area shall be provided for each  
78 occupant of such unit in excess of two."

79 Section 2. Section **15A-5-205** is amended to read:

80 **15A-5-205. Amendments and additions to IFC related to means of egress and**  
81 **special processes and uses.**

82 (1) In IFC, Chapter 10, Section 1008.2.1, Illumination level under normal power,  
83 delete exemption.

84 (2) In IFC, Chapter 10, Section 1010.1.9, Door operations, a new exception is added as  
85 follows: "Exception: Group E occupancies for purposes of a lockdown or a lockdown drill in  
86 accordance with Section 1010.1.9.5 Exception 5."

87 (3) In IFC, Chapter 10, Section 1010.1.9.2, Hardware height, "Exception:" is deleted

88 and replaced with "Exceptions: 1."

89 (4) In IFC, Chapter 10, Section 1010.1.9.2, Hardware height, Exception 2 is added as  
90 follows: "2. Group E occupancies for purposes of a lockdown or a lockdown drill may have  
91 one lock below 34 inches in accordance with Section 1010.1.9.5 Exception 5."

92 (5) In IFC, Chapter 10, Section 1010.1.9.3, Locks and latches, Item 6 is added after the  
93 existing Item 5 as follows: "6. Group E occupancies for purposes of a lockdown or a lockdown  
94 drill in accordance with Section 1010.1.9.5 Exception 5."

95 (6) In IFC, Chapter 10, Section 1010.1.9.4, Bolt locks, Exception 6 is added after the  
96 existing Exception 5 as follows: "6. Group E occupancies for purposes of a lockdown or a  
97 lockdown drill in accordance with Section 1010.1.9.5 Exception 5."

98 (7) In IFC, Chapter 10, Section 1010.1.9.5, Unlatching, Exception 5 is added after the  
99 existing Exception 4 as follows: "5. Group E occupancies may have a second lock on  
100 classrooms for purposes of a lockdown or lockdown drill, if:

101 5.1 The application of the lock is approved by the code official.

102 5.2 The unlatching of any door or leaf does not require more than two operations.

103 5.3 The lock can be released from the opposite side of the door on which it is installed.

104 5.4 The lock is only applied during lockdown or during a lockdown drill.

105 5.5 The lock complies with all other state and federal regulations, including the  
106 Americans with Disabilities Act of 1990, 42 U.S.C. Sec. 12101 et seq."

107 ~~[(2)]~~ (8) IFC, Chapter 10, Section 1010.1.9.6, Controlled egress doors in groups I-1  
108 and I-2, after existing Item 8 add Item 9 as follows: " 9. The secure area or unit with special  
109 egress locks shall be located at the level of exit discharge in Type V construction."

110 ~~[(3)]~~ (9) In IFC, Chapter 10, Section 1010.1.9.7, Delayed egress locks, Item 9 is added  
111 after the existing Item 8 as follows: " 9. The secure area or unit with delayed egress locks shall  
112 be located at the level of exit discharge in Type V construction."

113 ~~[(4)]~~ (10) In IFC, Chapter 10, Section [BE] 1011.5.2, Riser height and tread depth,  
114 Exception 3 is deleted and replaced with the following: " 3. In Group R-3 occupancies, within  
115 dwelling units in Group R-2 occupancies, and in Group U occupancies that are accessory to a  
116 Group R-3 occupancy, or accessory to individual dwelling units in Group R-2 occupancies, the  
117 maximum riser height shall be 8 inches (203 mm) and the minimum tread depth shall be 9  
118 inches (229 mm). The minimum winder tread depth at the walk line shall be 10 inches (254

119 mm), and the minimum winder tread depth shall be 6 inches (152 mm). A nosing not less than  
120 0.75 inch (19.1 mm) but not more than 1.25 inches (32 mm) shall be provided on stairways  
121 with solid risers where the tread depth is less than 10 inches (254 mm)."

122 [~~5~~] (11) IFC, Chapter 10, Section [BE] 1011.11, Handrails, is amended to add the  
123 following exception: " 5. In occupancies in Group R-3, as applicable in Section 1014 and in  
124 occupancies in Group U, which are accessory to an occupancy in Group R-3, as applicable in  
125 Section 1014, handrails shall be provided on at least one side of stairways consisting of four or  
126 more risers."

127 [~~6~~] (12) IFC, Chapter 10, Section 1013.5, Internally illuminated exit signs, delete and  
128 rewrite the last sentence to read "Exit signs shall be illuminated at all times, including when the  
129 building is not fully occupied."

130 [~~7~~] (13) IFC, Chapter 10, Section 1025, Luminous Egress Path Markings, is deleted.

131 [~~8~~] (14) IFC, Chapter 10, Section 1029.14, Seat stability, delete Exemption 2 and  
132 renumber exemptions.

133 [~~9~~] (15) IFC, Chapter 10, Section 1031.2.1, Security Devices and Egress Locks, is  
134 amended to add the following: On line three, after the word "fire", add the words "and  
135 building."